

SAFETY ALERT 01-S-8



FOREST RESOURCES ASSOCIATION INC.

600 JEFFERSON PLAZA, SUITE 350
ROCKVILLE, MARYLAND 20852

PHONE: 301/838-9385

FAX: 301/838-9481




FELLER-BUNCHER DESTROYED BY FIRE

February 2001

BACKGROUND: On a clear, sunny winter morning in the South a logger was felling pine trees with a feller-buncher machine.

PERSONAL CHARACTERISTICS: The operator was approximately 40 years old. He had been operating feller-bunchers and other logging machines for six years. He was trained to operate this particular machine.



UNSAFE ACT OR

CONDITION: No unsafe act or condition was identified. Prior to starting the feller-buncher in the morning, the operator and logging contractor had installed a new battery and a new starter and had cleaned the engine compartment. The contractor considered this maintenance routine work. He had removed and replaced countless batteries and starters without incident. No spilled or leading fuel or other hazard was observed during the morning "pre-start" inspection.

ACCIDENT: While operating the machine, the operator saw flames behind him on both sides of the cab, apparently emanating from the engine compartment.

INJURY: The operator bailed out of the machine with a fire extinguisher in hand, but he could not extinguish the fire. He was not injured. The feller-buncher was engulfed in flames and was destroyed.


RECOMMENDATIONS FOR CORRECTION: The insurance investigator could not determine an exact cause for the fire but suspected that a spark ignited fuel in or around the fuel system. Machine operators should always be alert to the possibility that their machines may start to burn even after they have conducted a thorough pre-start inspection and cleaning. Logging contractors should consider the merits of buying new machines with automatic fire suppression systems and installing such systems on older machines. To operate properly, an automatic fire suppression system must be regularly maintained.

REVIEWED BY:

Michael Wetzel
Southeastern Technical Division Forester

Please follow equipment manufacturers' recommendations for safe operation and maintenance procedures.





This Safety Alert analyzes an injury in accordance with the chain of events represented by the five dominoes at left. Pioneer industrial safety experts H. W. Heinrich and Alfred Lateiner developed this accident analysis system to provide a graphic sense of how injuries can be avoided. Their methodology has been accepted by safety professionals worldwide.

SAFETY MEETING REPORT

Date: _____ Company: _____

Topic(s) Discussed: _____

Names of Employees Attending:

_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

Conducted By: _____

Signed: _____

Comments / Recommendations:

